

## PRELIMINARY SUMMARY OF MAP ACTIONS

Community: LAKE COUNTY

Community No: 180126

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

**1. LOMCs Incorporated**

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
102	02-05-3080P	04/07/2003	SILVER HAWK PHASE 2	1801260105B	18126C0234E 18126C0253E
LOMR	05-05-A422P	06/30/2006	LAKE HILLS DEVELOPMENT	1801260080 1801260080B 1801260085 1801260085B	18126C0228E 18126C0229E

**2. LOMCs Not Incorporated**

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	92-05-121B	03/27/1992	LOT 13 DEEP CREEK TRAILS		18089C0267E
LOMA	93-05-0215W	11/02/1993	6420 E. 197TH AVENUE	1801260170B	18089C0375E
LOMA	94-05-1294A	12/14/1994	3329 EAST 109TH AVENUE	1801260120B	18089C0266E
LOMR-F	95-05-1416A	05/30/1995	493 LAKEVIEW COURT	1801260135B	18089C0333E 18089C0334E
LOMR-F	96-05-1892A	07/26/1996	245 ISLAND DRIVE	1801260135B	18089C0333E
LOMA	96-05-1002A	08/05/1996	442 LAKEVIEW COURT	1801260135B	18089C0333E 18089C0334E

## PRELIMINARY SUMMARY OF MAP ACTIONS

Community: LAKE COUNTY

Community No: 180126

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	97-05-172A	03/31/1997	LOT 10 - WESTRIDGE ESTATES - 17566 MAPLEWOOD	1801260130B	18089C0320E
LOMA	97-05-5062A	11/17/1997	DALE CARLIA SUBDIVISION - LOTS 39 & 40, BLOCK 15 - 1033 N. LAKEVIEW	1801260135B	18126C0334E
LOMA	99-05-7052A	10/15/1999	10336 W. 219TH AVENUE	1801260200B	18126C0130E
LOMA	00-05-2846A	06/28/2000	GREEN RANCHES ANNEX 2, LOT 21; 10620 PORTER STREET	1801260115B	18126C0242E
LOMR-F	00-05-6048A	02/16/2001	PORTION OF SECTION 31, T 35 N, R 8 W; WHITE HAWK COUNTRY CLUB	1801260105B	18089C0234E 18089C0253E
LOMA	01-05-2680A	07/11/2001	ASPEN TRAIL, LOTS 17, 19, AND 31	1801260080B	18126C0226E
LOMA	01-05-2446A	07/18/2001	PORTION OF SECTION 30, T 34 N, R 8 W; 4315 WEST 133RD AVENUE	1801260115B	18126C0244E
LOMA	01-05-2497A	07/27/2001	4321 WEST 133 AVENUE	1801260115B	18126C0244E
LOMA	02-05-1775A	04/17/2002	PART OF SECTION 30, TOWNSHIP 32 NORTH, RANGE 8 WEST; 3460 WEST 231ST AVENUE	1801260225B	18126C0435E 18126C0455E
LOMA	02-05-3177A	07/03/2002	SE 1/4 OF SW 1/4 OF SECTION 31, T35N, R9W; 13540 W 101ST AVENUE	1801260080B	18126C0220E 18126C0236E
LOMA	03-05-1766A	02/14/2003	TREES, UNIT NO. 4, LOT 51; 5872 EAST 105TH PLACE	1801260120B	18126C0267E
LOMA	03-05-1557A	02/12/2003	GRASSMERE, LOT 2; 22008 MONON ROAD	1801260225B	18126C0455E
LOMA	03-05-2315A	04/04/2003	SECTION 11, T35N, R9W; 1135, 1201, 1203, 1205 SOUTH CLINE AVENUE	1801260045B	18126C0143E
LOMA	03-05-3204A	06/18/2003	TREES, UNIT 4, LOT 52; 5898 E. 105TH STREET	1801260120B	18126C0267E
LOMA	03-05-5484A	10/31/2003	PORTION OF SECTION 29, TOWN 33 NORTH, RANGE 8 WEST, 2ND PM; 18805 CHASE STREET	1801260165B	18126C0375E
LOMA	04-05-0393A	11/14/2003	PART OF SE 1/4 SECT. 9, PART OF NE 1/4 SECT. 16, T34N, R8W	1801260115B	18126C0264E
LOMA	05-05-0259A	11/15/2004	5001 WEST 45TH AVENUE -- DUTCH GARDENS, BLOCK A, TRACTS 8 & 9	1801260045B	18126C0142E
LOMR-F	05-05-1641A	04/14/2005	SILVER HAWK - PHASE 2	1801260105B	18089C0253E

## PRELIMINARY SUMMARY OF MAP ACTIONS

Community: LAKE COUNTY

Community No: 180126

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	05-05-2864A	05/05/2005	3500 WEST 231ST AVENUE -- PORTION OF SECTION 30, T32N, R8W	1801260225B	18126C0435E 18126C0455E
LOMR-F	05-05-5197A	11/01/2005	GROUSE POINT SUBDIV, PHASE 1	1801260085B	18089C0229E 18089C0233E
LOMA	06-05-0315A	12/06/2005	GRASSMERE SUBDIV, LOT 1 -- 21942 MONON ROAD	1801260225B	18126C0455E
LOMA	06-05-B898A	05/04/2006	BITTERSWEET SUBDIV, LOT 3 -- 24270 CLINE AVENUE (IN)	1801260200B	18126C0445E
LOMA	06-05-BO74A	06/28/2006	133 JAMES ROAD -- PORTION OF SECTION 11, T35N, R9W (IN)	1801260045B	18126C0143E
LOMA	06-05-BS79A	08/23/2006	129 JAMES ROAD (IN) - A PORTION OF SECTION 11, T35N, R9W	1801260045B	18126C0143E
LOMA	07-05-3580A	05/24/2007	DALECARLIA, BLOCK 15, LOTS 43 & 44 -- 1041 NORTH LAKEVIEW DRIVE (IN)	1801260135B	18126C0334E
LOMA	08-05-0794A	12/06/2007	PON & COMPANY WILDWOOD SHORES, LOTS 126-128 -- 6114 WEST 249TH AVENUE (IN)	1801260200B	18089C0445E
LOMA	08-05-3938A	07/22/2008	PON & COMPANY'S WILDWOOD SHORES, LOT 138 -- 5912 WEST 248TH PLACE	1801260200B	18089C0445E
LOMA	08-05-4686A	08/29/2008	PORTION OF SECTION 35, T33N, R9W -- 6812 BELSHAW ROAD	1801260145B	18089C0343E

## 3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
LOMA	199300285R05	10/15/1993		1
LOMR-F	05-05-1153A	02/01/2005	PRAIRIE ESTATES DEVELOPMENT, PHASE 2, UNIT 3	1
LOMA	07-05-5095A		Lot 1, M K & G Acre Subdivision - 23103 Pierce Street	1
LOMA	09-05-0249A		Lot 184, Waterside Crossing Phase 3 Subdivision - 10360 Illinois Street	1

**PRELIMINARY SUMMARY OF MAP ACTIONS**

Community: LAKE COUNTY

Community No: 180126

1. Insufficient information available to make a determination.
2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
4. Revised hydrologic and hydraulic analyses.
5. Revised topographic information.

**4. LOMCs To Be Redetermined**

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		